

E.C.3

2m. 10.30.

*Vessel requires to be further examined
at next drydocking (after grounding)*

nt to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

American Trader

Report

No.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/32.)

~~Area of Survey~~

2nd S.S. No 1 ~~When due~~ *7.40*

Class withdrawn at Owners' request.

RLD

14.10.40

Insert in RB ...



© 2021

Lloyd's Register
Foundation

006857-006867-0141