

Chief Ship Surveyor 16.10.13

Received from Chief Ship Surveyor

AME *Icebreaker Tung-Ling* Rpt. *Chi* No. *1451*

Requests of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.


The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

by *Fired Entry*

It is submitted that before this case receives the consideration of the Committee the Superintendent of the Tipton Proving House should be requested to forward particulars of the test of three anchors, the certificate numbers of which are 68876, 68875 and 68883 and which were tested on 17.2.13, 1.2.13, and 17,2,13 respectively.

At the same time the Superintendent of the Tipton Proving House should be requested to forward particulars of the tests of a stream anchor, Certificate No. 40351 tested 5.2.13, and also of 46½ fathoms of 10/16" chain cable, the non-statutory certificate No. of which is 27618 and which was tested 5.2.13: also for the tests of 165 2/3rds fathoms of 1" chain cable, the certificate no. of which is 41514 and which was tested 11.2.13.

10.13



Lloyd's Register  
 Foundation