

COPY

Lloyd's Register of Shipping.

MEIKAI BUILDING

32, AKASHI-MACHI,

KOBE.

19th July 1933.



CERTIFICATE No. 3599.

This is to Certify that at the request of Messrs. The Kobe Steel Works, Ltd., Kobe, attend at their works on the 11th April 1933 and subsequent dates for the purpose of surveying during construction, two sets, two stage air compressors having cylinders, H.P. 310 m/m dia. and L.P. 340 m/m dia. by 180 m/m strokes.

The cylinders were tested by hydraulic pressure to 60 Kg/cm² internally and to 10 Kg/cm² and 2 Kg/cm² on the jacket side, and found sound and tight.

The H.P. coolers and connections were water tested to 60 Kg/cm² and jacket space to 5 Kg/cm² and found in order.

The L.P. coolers and connections were water tested to 7.5 Kg/cm² and jacket space to 5 Kg/cm² and found in order.

The compressors were finally assembled and tested under working condition on the 19th June 1933 connected to auxiliary diesel generators and found satisfactory.

After shop trial the machines were overhauled and examined, and found in good order.

These machines are intended for Harima Shipbuilding and Engineering Co. Ltd., Ship No. 189, and have been stamped as follows:-

LLOYD'S
No. 3599A
27-6-33
H.A.G.L.R.

LLOYD'S
No. 3599B
17-7-33
H.A.G.L.R.

Fee.....Y 100:00
Expenses.....£ 3:00

M. K. Garnett
SURVEYOR TO LLOYD'S REGISTER.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

“While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society.”

COPIES
REGISTERED
MEIKAI BUILDING
32, AKASHI-MACHI,
KOBÉ.
JAN 11 1909
AIR COMPRESSOR
189
COPY 189

guygind to pteipad a'bgoll

MEIKAI BUILDING

35, ANAHI-MACHU, HOAM-1H2ANA

KOBÉ



• 333 •

This is to Certify that

[illegible]

100-443887-100

Page 13 of 13

2. The following information was obtained from the records of the Bureau of Census:

[illegible]

1. The first step is to identify the problem or question that needs to be answered. This involves understanding the context and the specific requirements of the task.

[Faint, illegible text]

1954

Ad: 001 Y 005
on 28 Y 005

Wm. J. R.

“While the Committee use their best endeavors to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors or other Officers or Agents of the Society.”