

Received by Chief Ship Surveyor

18/3/13

Received from Chief Ship Surveyor

VESSEL'S NAME

H. S. Dogger Bank Rpt. April

No. 25972

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

First entry

It is submitted that before this case receives the consideration of the Committee the Hull Surveyors should be requested to state whether they are correct in reporting that there are 165 fathoms of 1" chain cable on board, in view of the Rules requiring the vessel to be supplied with 120 fathoms of $1\frac{1}{8}$ " cable.

R. 20/3/13

M

19. 3. 13

© 2021

Lloyd's Register
Foundation

006368-006876-041