

COPY



LLOYD'S REGISTER OF SHIPPING

MEIKAI BUILDING

No. 32, AKASHI MACHI,

KOBE, November 5th 1936.-

TELEGRAMS: "REGISTER" KOBE
TELEPHONE: 2530 SANNOMIYA

Messrs. Mitsui Bussan Kaisha, Ltd.,
Superintendents Department,
K O B E

Attention: Mr. Kawai.

Dear Sirs,

With reference to the vessel No.212 ("OMROSAN MARU"), now building at Tama Yard, we have to say that in the left hand combustion chamber of the exhaust Gas boiler, the tube plate is slightly deformed, stated to have been caused by placing a heavy weight on the tube plate after the combustion chamber had been made and before it was fitted in the boiler.

The strength of this tube plate, calculated by the Society's Rules, is ample to allow for any bad effect which may arise due to this deformation, and as no signs of weakness were observed during the hydraulic test, it is proposed to recommend this boiler for Classification, subject to your consent being obtained.

In the circumstances, we shall be glad if you will confirm, in writing, that you are willing to accept the above boiler with this slight defect.

We are, Dear Sirs,
Yours faithfully,

C. Macpherson & *M. Kawakura*

© 2021 Lloyd's Register Foundation

006903-006911-0104