

3m.7.40.

11 AUG 1941

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME BANDOENG MARU Rpt. Yka No. 7087

**The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.**

(“The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.”—*Extract from Sub-Committee's Report, 24/5/92.*)

The class is subject to indented shell plates No. 4 in 2nd strake and Nos. 3 and 4 in 3rd below sheer from aft (s.s) being permanently repaired at the first convenient opportunity, and to a bower anchor being supplied at the earliest opportunity.

The YOKOHAMA Surveyors report the vessel placed in dry dock, bottom coated, and 2 lengths of chain cable renewed.

It is submitted the vessel appears worthy to remain as classed with record of survey 4.41, subject as above.

100A1        )  
4.41 Yka     ) Subject, etc.

PLATING to be DRILLED when vessel is 24 years old, or at next Special Survey thereafter.

*Handwritten initials and date: 5.8.41*



© 2021

Lloyd's Register  
Foundation

006930-006941-0057