

1  
Sent to Chief Surveyors

Received from Chief Surveyors

10/6

VESSEL'S NAME

"YORICK"

Report

Lon.

No.

107418a

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/6/02.)

Nature of Survey

When due

No Survey is due on the hull of this vessel.

The Aberdeen Surveyors now write enclosing a letter from the Owners to the effect that they desire this vessel to be withdrawn from classification.

It is submitted the class of this vessel be withdrawn from the Register Book and Three Dots (...) inserted in lieu thereof, indicating withdrawal of class at Owners' request.

Withdraw class

Insert (...)

*ggg* *h/l*  
9.6.39.



© 2021

Lloyd's Register  
Foundation

006930-006941-0222