

Steel Steam Trawler "YORICK", building at Hull with  
a view to classing 100A1 "Stm Trawler".

The chain cables ~~is~~ stated to be required by the Rules  
for this vessel is 90 fathoms of 1" <sup>short</sup> ~~stud~~ link having a weight  
of 49 cwts. 2 qrs. 0 lbs., and that supplied 90 fathoms of 1"  
<sup>short</sup> ~~stud~~ link having a weight of 48 cwts. 3 qrs. 7 lbs., or a  
deficiency of 2 qrs. 21 lbs, or about 1% in weight. The  
Surveyors state that the Owners attention has been drawn to the  
deficiency in the weight of the chain cables, and that they are  
prepared to accept the same, provided the chain as supplied meets  
with the Committee's approval.

In view of the slight deficiency in weight, the  
chain cables are submitted for the approval of the Committee.

TUES. 17 AUG 1909

approved W.

R. 16.8.09  
Asad 17.8  
1 cont.



© 2021

Lloyd's Register  
Foundation

006930-006941-0228