

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of London

No. in Reg. Book. 336 on the Wood, Iron or Steel & John Donovan Date, First Survey Master a Rigby

TONNAGE:- GROSS 206 Built at Newcastle By whom J.T. Eltringham & Co. Ltd When 1914 8

UNDER DEK 203 Owners R. Hastie & Sons Port belonging to N. Shields

NET 28 Owners' Address (if not already recorded in Appendix to Register Book). Destined Voyage

Surveyed Afloat or in Dry Dock? Name of Dock Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

WB=CellDBorDBa feet; uE&B feet; f feet; } total capacity tons. FPT tons; APT tons; MT feet tons. } CHARACTER. X for Special Survey. Date of last Survey and of Periodical Surveys.

Y.B.—All alterations in the existing records should be underlined. If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

I set Report, No. 77270 Port Was a damage report made by anyone else? If so, by whom?

OR EXAMINATION AS PER RULE, FOR

DAMAGE REPAIRS :—		Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :—
Faired or Repaired									
Repaired in place									
ON OF THE		Stringers	Dbng. Plates under Sounding Pipes				Copper, or Y.M. of Wood Vessels. (State if on Felt.)		
		Inner Bottom Plating	Engine Room Skylights				When put on, Month Year		
		State if Tanks have been examined inside	Coal Bunkers, Open'gs, Lids, &c.				Boats		
		State if Tanks now tested	Scuppers				Masts, Yards, &c.		
		Bulkheads	Cargo Hatchways				Condition, how ascertained		
		Ceiling	Hatches				(State if wedges removed)		
		Cement or Asphalt (State which.)	Planking of Wood Vessels				Sails		
		Rudder	Caulking ditto				Equipment letter		
		Steering gear and its connections	Treenails ditto				Anchors, No. of		
		Windlass	Breasthooks & Stemson ditto				Cables (State if now ranged)		
		Have Pumps now been examined and found efficient?	Transoms, Pointers, & Crutches ditto				length size (on board)		
		Have Sluice Valves now been examined and found efficient?	Timbers of Frame at openings ditto				Rule length size		
		Have Watertight Doors now been examined and found efficient?	Ditto ditto at other places ditto				Hawser & Warps		
			Stringers, Clamps & Shells ditto				Standing & Running Rigging		
			Salting ditto						
			(State if examined.)						

Observations, Opinion as to Class, Recommendation, &c.:—

Survey Fee (per Section 25)	£	:	:	Fees applied for,	10
Special Damage or Repair Fee (if any) (per Sec. 29)	£	:	:	Received by me,	10
Travelling Expenses (if chargeable)	£	:	:		
Second Surveyor's Fee (if any)	£	:	:		

Committee's Minute Character Assigned

Surveyor to Lloyd's Register of Shipping. General Committee Thursday, 17th July, 1919. Lloyd's Register of Shipping. Classing Committee's decision confirmed