

DISCLOSED SECTION REPORT OF SURVEY FOR REPAIRS, &c.

(Received at London Office)

No. 109033

Date of writing Report 19... When handed in at Local Office 19... Port of London

No. in Survey held at Date, First Survey Last Survey

325

77242 on the Wood, Iron or Steel Twp. Sc. steamer "Katori Maru"
TONNAGE:- Built at Kawasaki By whom Mitsui Bishi Shyda. & Wks. When 1913 9
GROSS 9849 Owners Nippon Yusen K.K. Owners' Address
UNDER DK 8060 Managers Port belonging to Tokyo
NET 6128

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage
Cell DBor DBa feet; uE&B feet; f feet
total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.

Last Report, No. 11546 Port Kob

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Machinery and Boiler Surveys (Including date of N.B., if any).
+100 A1	+LMC 4-38
6-40	B 6-40
	Ch 640
No Yka Ins no-3-4-38	

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined
Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.
Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE		Copper, or Y.M. (State if on Felt.) When fitted, Month Year
Decks	Bulkheads	Boats
Caulking of Decks	Ceiling	Masts, Yards, &c.
Coamings	Cement or Asphalt	Condition, how ascertained (State if wedges removed.)
Beams & Fastenings	Rudder	Equipment letter
Outside Plating	Steering gear and its connections	Anchors, No. of
" " in way of sidelights	Windlass	Cables (State if now ranged)
Frames	Have pumps been examined and found efficient?	" length (on board) mean diam.
Reverse Frames	Have Sluice Valves been examined and found efficient?	" Rule length size
Longitudinals	Have Watertight Doors been examined and found efficient?	Chain Locker
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Hawsers & Warps
Floors	Air and Sounding Pipes	Standing and Running Rigging
Keelsons	Doubling Plates under Sounding Pipes	Sails
Stringers		
Inner Bottom Plating		
Have the Tanks been examined internally?		
Have the Tanks been tested?		

General Observations, Opinion as to Class, Recommendation, &c. :-
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Survey Fee (per Section 20)	Special Damage or Repair Fee (if any) (per Sec. 20)	Travelling Expenses (if chargeable)	Second Surveyor's Fee (if any)	Fees applied for, 19	Received by me, 19
£	£	£	£		

Committee's Minute TUE. 28 JAN 1941
Character Assigned 8 Omit class and reprint of Reg. Bk. Class omitted from Reports JRM



23 JAN 1941

10m. 3. 40.—Transfer Ink (MADE AND PRINTED IN ENGLAND) (The Surveyors are requested not to write on or below the space for Committee's Minutes.)

Is Certificate required? If so, to be sent to 007045-007058-0210