

y Chief Ship Surveyor

Received from Chief Ship Surveyor

23 DEC. 1921

S NAME

Att. Sc. "Pavia"

Report

Sun

No.

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey

2nd S.S. No. 3.

Classification

THICKNESSES OF PLATING ascertained by drilling, and comparison of same with the original thicknesses.

The thicknesses are in ^{ths}20 of an inch.

STRAKE.	AMIDSHIP.					*FORWARD.					*AFT.					REMARKS.
	Original Thick-ness.	Thickness by drilling.		Diminution if any.		Original Thick-ness.	Thickness by drilling.		Diminution if any.		Original Thick-ness.	Thickness by drilling.		Diminution if any.		
		Port.	Std.	Port.	Std.		Port.	Std.	Port.	Std.		Port.	Std.	Port.	Std.	
	Ins.	In.	In.	In.	In.	Ins.	In.	In.	In.	In.	Ins.	In.	In.	In.	In.	
1 SHEER STRAKE																
2 below																
3 SHEER STRAKE	11	11	10½	·	½	8	8	8	·	·	8	8	7	·	1	
4 STRAKE below	6	5	6	1	·	5½	5	5½	½	·	5½	5	5	½	½	
5 " "	7	6	6½	1	½	6	6	7	·	·	6	6	6	·	·	
6 " "	6	6	5½	1	½	5½	5	5	½	½	5½	5	4½	½	1	
7 " "	8	6½	7	1½	1	7	7	6	·	1	7	7	7	·	·	
8 " "	7	7	7	·	·	6	5	5½	1	½	6	5	6	1	·	
9 " "																
10 " "																
11 " "																
12 " "																
13 " "																
14 " "																
15 " "																
16 " "																
17 " "																
18 " "																
19 " "																
20 " "																
21 " "																
22 " "																
23 " "																
24 " "																
25 " "																
26 " "																
27 " "																
28 " "																
29 " "																
30 " "																
31 " "																
32 " "																
33 " "																
34 " "																
35 " "																
36 " "																
37 " "																
38 " "																
39 " "																
40 " "																
41 " "																
42 " "																
43 " "																
44 " "																
45 " "																
46 " "																
47 " "																
48 " "																
49 " "																
50 " "																
51 " "																
52 " "																
53 " "																
54 " "																
55 " "																
56 " "																
57 " "																
58 " "																
59 " "																
60 " "																
61 " "																
62 " "																
63 " "																
64 " "																
65 " "																
66 " "																
67 " "																
68 " "																
69 " "																
70 " "																
71 " "																
72 " "																
73 " "																
74 " "																
75 " "																
76 " "																
77 " "																
78 " "																
79 " "																
80 " "																
81 " "																
82 " "																
83 " "																
84 " "																
85 " "																
86 " "																
87 " "																
88 " "																
89 " "																
90 " "																
91 " "																
92 " "																
93 " "																
94 " "																
95 " "																
96 " "																
97 " "																
98 " "																
99 " "																
100 " "																

* The thicknesses given in these columns should indicate the actual thicknesses at not less than one-fourth the vessel's length from each end.

This vessel was built by the Lloyd Austriaco in 1899 and ~~is~~ was classed with the Veritas Adriatico.

With a view to classification with this Society the scantlings and arrangements as indicated on the plans were examined and found such as could be recommended for approval for the class A1 "For Service in the Adriatic" provided the pillaring arrangements throughout be found ^{or made} to the Surveyors' satisfaction.

The Fiume Surveyor now forwards the results of the drillings as shown above.

It is submitted the drillings be accepted and the Surveyor should be informed accordingly and requested to forward a First Entry Report on completion of the survey.

22.12.21.