

16

24 MAY 1950

Ship Surveyor

Received from Chief Ship Surveyor

NAME

'O K S Y W I E'

REPORT

Gdy.

No. 3233

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

ACTION and NOTATION of 'ss. Gdy. 2.48' are DEFERRED for completion of Special Survey by repairs and for examination in dry dock after grounding.

Permanent repairs required to shell plates A.3, 4 & 5 and B.3, 4 & 5 (s.s.) with internals in way by 4.50, and 15 fathoms of chain cable renewed.

The GDYNIA Surveyors report, the vessel afloat and in consequence of previously reported grounding further temporary repairs have been effected to the set up bottom plating, etc. in way of No.5. D.B. tank and permanent repairs recommended at the next dry docking.

IT IS SUBMITTED ACTION and NOTATION of 'ss. Gdy.2.48' continue to be DEFERRED for completion of Special Survey by repairs and for examination in dry dock after grounding.

IN S.R.L.

Dry docking (grounding).

INSERT IN S.R.L.

Buckled structure in No.5.
D.B. tank to be dealt with at
the next dry docking.

ENDORSEMENT OF CLASS (B).

Indents in shell plating (p & s).

TO COMPLETE S.S. :-

Damage repairs.



© 2020

Lloyd's Register
Foundation

007072-007077-0023