



Lloyd's Register of Shipping,

17 Battery Place,

New York.

November 29th, 1927.

LLOYD'S REGISTER
RECEIVED
-7 DEC 1927
Aired
LONDON

Dear Sir:-

S.S. "ROMA"
No. 3340 in the R.B.

I have to inform you that there appears to be some misunderstanding regarding the working pressure of the boilers of the above mentioned vessel.

The Register Book gives the working pressure as 200 pounds. The Engineers of the vessel maintain that the working pressure is 220 pounds and during the recent inspection by U.S. Government Inspectors a test pressure of 330 pounds was applied.

I shall be much obliged if you will inform me which pressure is correct, in order that I may inform the Owners Superintendent accordingly.

Yours faithfully,

John S. Heck

The Secretary,

London.

JSH:DB



© 2020

Lloyd's Register
Foundation

007072-007072-0161

Referred to the Chief Engineer Surveyor.

af

-7 DEC 1927

South 2nd

New York

14 BUNCE PLACE

Printed in England



© 2020

Lloyd's Register Foundation

SURVEY
ELEPHANT