

Register
as out on B
LENGTH

Chief Surveyors 3.6.14

Received from Chief Surveyors

NAME Steel Lum-S/S

Robina

Report

SL

No. 34072

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey

1st Sub-

When due

A - (Steel) Irish Channel Service

10K.

EK. 5BH. Asp. B 63'

M
6.14
4

the Surveyors should be informed it is concluded
the additional w.t. bulkhead fitted on frame
No 12 has been constructed & stiffened similar
to the other bulkheads & that a record of 5BH.
should be made in the Register Book.

Dr SL 11.6.14

M
6.14
4



© 2021

Lloyd's Register
Foundation

0000-007087-0080

BEAMS,