



Lloyd's Register of Shipping,

97 & 98, Scottish Provident Buildings,
Donegall Square West,

Belfast, 30th December, 1926

Reference

The Secretary,
LONDON.

LLOYD'S REGISTER
Recd. 31 DEC. 1926
Ans'd.
LONDON

Dear Sir,

With reference to Belfast Report No. 9662 on
the installation of Electric Light on the T.S.S. "ROBINA",
I have to state that a compass has not yet been readjusted
since the installation was completed. The Owners do not
propose to have this done until the vessel is re-examined
in March for her Board of Trade Certificate.

As this vessel's duties are confined to Belfast
Lough it was not considered advisable to hold up the report
until this requirement was fulfilled.

I am, Dear Sir,

Yours faithfully,

B. F. Southwell

pro. The Surveyors.

1 enclos.



Lloyd's Register
Foundation

007078 - 007087 - 0086

Referred to the Chief Engineer Surveyor.

31 DEC 1926

Also for Mr. S. A. Hill to note.



© 2021

Lloyd's Register
Foundation