

Ept. 8.

No. 53004

# REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report... 24-7-1945 When handed in at Local Office... 24-7-1945 Port of... HULL  
No. in Reg. Book... 11485 Survey held at... Hull Date, First Survey... 13-4-45 Last Survey... 16-4-1945  
on the Wood, Iron or Steel... STEAM TRAWLER NEPTUNUS (No. of Visits... 3)

TONNAGE :- Built at Glasgow By whom Mackie & Thomson When 1902 MONTH 12  
GROSS 171 Owners Royal Netherlands Govt Owners' Address...  
UNDER DK 171 Managers... Port belonging to...  
NET 62

Surveyed Afloat or in Dry Dock? afloat Name of Dock St Andrew Dk Destined Voyage...  
Cell DBor DBa... feet; AE & B... feet; f... feet }  
total capacity... tons. FPT... tons; APT... tons; MT... feet tons. }  
Only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.

Last Report, No. 89668<sup>A</sup> Port Lon.

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER.	Machinery and Boiler Surveys (Including date of N.B., if any).
* For Special Survey. Date of last Survey and of Periodical Surveys.	
+	+
2.26	
Stm Trawler	
Unclassed Trawler.	
SS Gms 203-3-19	
SS Gms 201-2-3	
Society's Freeboard (if assigned) as painted on Ship and now verified	— ft. — ins.

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR damage stated to have been caused by grounding in Aberdeen Harbour on 23<sup>rd</sup> June 1945  
Now done

Vessel examined whilst lying afloat, (bunkers and aft fishroom full of coal) Machinery spaces and fishroom examined no leakage observed or damage noted  
It is recommended that a further examination be held in drydock or slipway at first convenient opportunity.

SUMMARY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed ...								
Removed and Faired or Repaired								
Faired or Repaired in place ...								

## PRESENT CONDITION OF THE

Decks	Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Felt.)
Caulking of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year
Coamings	Cement or Asphalt	Oil Bunkers	Boats
Beams & Fastenings	Rudder	Scuppers	Masts, Yards, &c.
Outside Plating	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained (State if wedges removed.)
" " in way of sidelights	Windlass	Hatches	Equipment letter
Frames	Have pumps been examined and found efficient?	Planking	Anchors, No. of
Reverse Frames	Have Sluice Valves been examined and found efficient?	Caulking	Cables (State if now ranged)
Longitudinals	Have Watertight Doors been examined and found efficient?	Trunnels	" length mean diamr. (on board.)
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stenson	" Rule length size
Floors	Air and Sounding Pipes	Transoms, Pointers & Crutches	Chain Locker
Keelsons	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Hawsers & Warps
Stringers		" " at other places	Standing and Running Rigging
Inner Bottom Plating		Stringers, Clamps & Shelves	Sails
Have the Tanks been examined internally?		Salting (State if examined.)	
Have the Tanks been tested?			

## General Observations, Opinion as to Class, Recommendation, &c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example :- "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

For the information of the Committee only.

Survey Fee (per Section 29)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 29)	£	5	5	0 25 JULY 1945
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19

Committee's Minute

Character Assigned

Noted - not for classing Committee

John Douglas  
Surveyor to Lloyd's Register of Shipping.

© 2021

Lloyd's Register Foundation