

Sent to Chief Surveyors

22 DEC 1924

VESSEL'S NAME

*S. S. Observador*

Received from Chief Surveyors

Report

*hon*

No. *88459<sup>e</sup>*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

*Screw Shaft*

When due

*9.24.*

The screw shaft became due for survey in September last.

The Buenos Aires Surveyors now state they are informed by the Owners that they do not intend to continue the vessel's class.

It is submitted that the vessel's class be withdrawn from the Register Book & three dots (...) inserted in lieu thereof indicating withdrawal of class at Owners request.

Withdraw class  
Insert ...

*ARK*

*A.S.*  
19/12/24.

*P.M.*

*M.S.*



© 2021

Lloyd's Register  
Foundation