

Two 100 Ton Wood Barges AMP40 & AMP41.

Captain McLellan, of the Eagle Oil Transport Co.Ld., states, per 'phone, that he understands that the wire ropes and cables for these barges were according to Lloyd's requirements and that certificates for the same have been sent to Valparaíso, but they have no record that the anchors purchased were according to Lloyd's requirements and he does not think that any certificates for the same are available.

SAH.

28.11.23.

The Chief Ship Surveyor

70 NO 25/11/23

© 2021

Lloyd's Register
Foundation

007150-007160-0070

but that no action be taken in regard to equipment

29.11.23.