

Chief Ship Surveyor \_\_\_\_\_

Received from Chief Ship Surveyor \_\_\_\_\_

NAME Ferro. Concrete Tug "CRETEBLOCK" Rpt. L on. No. 83241.

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey First Entry.

The Sunderland Surveyors should be advised that to complete the Survey, the Engine room skylight & Boiler Room fidky casings are to be fitted, the decks to be tested after fittings are in place, pumping arrangements to complete, & the windlass & Steering Gear to be tried; and they should be requested to form a report in form B when the Survey has been completed

30.6.20.

SUNDEI



att. 2021  
30-6-20

Lloyd's Register  
Foundation

007150-007160-0160