

COPY.

SHANGHAI (cont).

4278 "KUT WO" Particulars are desired regarding the testing of anchors and chain cables, steering chains, stream wire, tow line, hawsers and warps.

4279 "TUCK WO" As it is understood this vessel was sunk by bombs in December, 1937, it is not proposed to make any enquiries in regard thereto.

4333 "KUNG WO" I shall be glad to learn whe ther cargo battens or are not are/fitted and to receive the necessary particulars regarding the origin and testing of chain cables etc., together with the overall length of the vessel.

4468,69,73,75, As recommended.



© 2021

Lloyd's Register
Foundation

007150-007160-0225