

Do. of Forecasts  
Do. of Houses on Deck  
Do. of ...

Urgent

D. S. 335

F.E.

Received by Chief Ship Surveyor 24. 4. 07

Received from Chief Ship Surveyor

VESSEL'S NAME Sa. S. S. "Period" Rpt.  hull No. 5011

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	2/20"	Proportions
Spar Sheerstrake . .		
Description of Framing:— <u>Deep (Bulb angle) framing, as approved.</u> (viz., ordinary, deep, zed, channel or bulb-angle).		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed † 100 A 1 ("Steel").

† 100 A 1 ("Steel")

Spar Deck (Stc) & deep framing, cantilever framed, topside tanks. Spar Deck Rule.

N. B = Cell DB a 106' in E & D 35' f 135' 657c Topside tanks P 246' S 256' 626c FPT 82c APT 132c

FK 5BH Cam. Leaps A & CP B 58' F 39' HS lengthened 6.43

*YBH*



© 2021  
24/4/07  
Lloyd's Register  
Foundation

007168-007176-0138

5c, 8, 6.

Average space .....  
PILLARS, In 'tween Deck