

16 NOV 1924

nt to Chief Surveyors.

Received from Chief Surveyors

VESSEL'S NAME Stl. Sc,K. "MANIN"

Report

Lon.

No. 88362A

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report 24/5/02.*)

ature of Survey

When due

Notation of s.s. Bcl.(2nd) No.1-24 has been assigned to this vessel.

The Barcelona Surveyors now state the Owners have requested that the class of the vessel be withdrawn from the Register Book.

It is submitted the vessel's class be withdrawn from the Register Book and three dots (...) inserted in lieu, indicating withdrawal of class at Owners' request.

Withdraw Class

Insert ...

14.11.24.

*[Handwritten signatures and initials]*

© 2021

Lloyd's Register Foundation

007177-007190-0227