

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

10 JAN 1924

VESSEL'S NAME Wood Sc. "GREYNIGHT" Rpt. Gms. No. 13755

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey _____

The class of this vessel was withdrawn from the Register Book on the 7th June last and three dots (...) inserted in lieu, indicating withdrawal of class at Owners' request.

The Grimsby Surveyors subsequently stated that the Owners were considering the advisability of having the class reinstated, and were informed that provided the vessel ^{was} ~~is~~ generally examined and favourably reported upon the class would be reinstated.

The same Surveyors now report the vessel has been placed in dry dock, the bottom recoated and a general examination made, and the vessel found to be in a satisfactory condition.

It is submitted the vessel appears worthy to have her class reinstated in the Register Book with record of survey 12,23 Gms.

Reinstate +11A1

For fishing purposes.

12,23 Gms.

Lloyd's A&CP 9 and 12 yrs mat.



© 2021

Lloyd's Register Foundation