

This vessel's class was withdrawn at Owners
request in June last
A survey for recertification now held
Screwshaft drawn

N.B. - If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

It is submitted that
this vessel is eligible for
THE RECORD. + L. M. C 12.23

S. 12.23. C.L.

Reinstated to B. pass / Polls
(S)

J.P.
10/1/24

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2021

Lloyd's Register
Foundation