

CABLEGRAMS: NYMDIBLE, NEW YORK.

TELEPHONES { 0220 } WHITEHALL - 4  
                  { 0221 }  
                  { 0222 }  
                  { 0223 }



Please address  
further communications  
on this subject to  
THE PRINCIPAL SURVEYOR

# Lloyd's Register of Shipping,

17 Battery Place,

New York.

LLOYD'S REGISTER  
Received  
- 5 JAN 1940  
Anad.  
LONDON

December 21, 1939

Dear Sir:

"LEOLA VIVIAN"

I am forwarding herewith Vancouver Surveyor's First Entry Report No. 5316 on the above named vessel, which is Vivian Yard Marpole Hull No. 1. The following plans and reports are also enclosed:

- Two prints of Midship Section
- Rudder and rudder assembly
- Rudder casting report
- Crankshaft
- Tail Shaft
- Pumping arrangement
- Oil fuel tanks
- Air receiver
- Engine shafting test reports
- Air receiver report
- Photo of auxiliary engine

It will be noted that the main scantlings of the vessel as built are in accordance with the latest approval, a copy of which was forwarded to you with my letter of the 30th March last.

The chain cables for the vessel have not yet been delivered and in these circumstances it is suggested that assignment of the Figure 1 might be deferred, pending receipt of particulars of the chain cable.



© 2021

Lloyd's Register  
Foundation

007257-007265-0189 1/2

Number of Breasthooks	2	Pointers		Curtains	
Butt End Bolts are of		in the Bottom		Bolts in each Butt End	
				through and cleanc	



