

2m.10.39.

Only alterations in the existing records of tanks should be inserted.

100A1 2-40

Yka. 2nd No

Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

Toyohasi Maru

Rpt.

Yka

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classification Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the facts presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

Society's Freeboard (if painted on Ship and

else? If so, by whom?

Damage repairs.

frame, and rudder

tween deck spaces,

tion.

Signature of Surveyor

DAMAGE.

Damage through

Heavy Weather.

now repaired as follows:-

	Shell Plates	Main Frames	R. Frames	Floors & Bracket Floors	Beams	Inner Bottom Plates	Deck Plates
Renewed					—	—	—
Removed and faired or repaired.....					18	—	14
Faired or repaired in place.....					—	—	2

Other items:- *13 Pillars renewed
Minor repairs effected*

*Vessel placed in dry dock & bottom coated.
Due to wear & tear 7 shell plates renewed and 1 doubled.
2 upper and 2 poop deck plates ren*

It is submitted the vessel is worthy to remain as classed with record of Survey 5,41

100A1.

5,41 Yka.



Recommendation, &c.:-

classification and notification of the vessel in Book without fresh record of Survey, "to remain p. 1-38." and eligible in my opinion

Survey 5-41.

007266-007275-0147

Vertical text on the left edge of the page.