

mfr. "San Ramon".

LA. 2835.

The Cloyd's Agents at Vera Cruz have been asked to state whether the oil engines were run out & examined for Annual Survey last November.

No mention is made of this in their letter now received.

The size of the screw shaft is also required. It is submitted Cloyd's Agents should be asked to reply to these inquiries.

Lr Ky. 2/8/23