

13th April, 1923.

LLOYD'S REGISTER
NEW YORK
APR 21 1923

Lloyd's Register of Shipping,
Battery Place,
New York, USA.

LLOYD'S REGISTER,
LONDON.

REC-1 1923

Sirs:

ANS

Aux. Schoer. "SAN RAMON"

It is but with deep regret that we beg to refer to your letters of September 14th, December 18th, February 2nd and March 1st, relating to sizes and test markings stamped upon the shafts and propellers of said Aux. Schooner, as we have been unable even to this date to obtain a complete and reliable information in the case as you desire, for any cause or the other.

According to a report on this Ship's Machinery rendered to the Register's London Office by our Surveyor, on the basis of the information, it appears that the dimensions of shafts are as follows: Tunnel shaft as fitted: 6-5/8"; Thurst shaft as fitted: 6-5/8".

As to the stamping of the crank shafts, we may inform you that we have seen a Report rendered under date of March 7th, 1918 by Mr. W. Lawson, Surveyor to Lloyd's Register at San Francisco, stating that they are marked thus:

	<u>Lloyd's.</u>		<u>Lloyd's.</u>
No. 136 Shaft	No. 545.	No. 136 Shaft	No. 215.
	31-7-17.		<u>R.B.5-17.</u>
	<u>W.S.</u>		

We have been informed by the Owners that this vessel is to be in this Port next week and we will recommend our Surveyor to verify the above marks in order that we may inform you afterwards of the result.

Apologizing for our delay in answering to your mentioned letters we beg to remain, Dear Sirs,

Yours faithfully,

Lloyd's Agents.



© 2021

Lloyd's Register
Foundation

007276-007287-0077