

Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

NAME WOOD Aux. Sc. "JAYO" Rpt. NFL No. 1145

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/82.)

Survey First Entry.

This vessel has been built in accordance with the approved plans and It is submitted, this Vessel appears worthy to be classed

9 A.1. "sailed".

1 DK.

A. & C.P. Q 68'

M acc.
18.9.19

It is concluded drip ways have been fitted in way of oil tanks, to prevent leakage of oil into bilges or saturation of woodwork.

yes.
see letter
13-10-19.



© 2021

Lloyd's Register
Foundation

007276-007281-0100