

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 11-1-13 Port of GRIMSBY.
No. in Survey held at GRIMSBY. Date, First Survey 28-12-12 Last Survey 7-1-1913
Supplement on the Wood, Iron or Steel to K. "FENTONIAN" (No. of Visits 4) Master
TONNAGE:- Built at Selby. By whom Lochrane & Sons Ltd. When 1912.
GROSS 230 Owners H. Bent. Hoop & S. R. Ld. Port belonging to Grimsby.
UNDER DE.
NET Owners' Address (if not already recorded in Appendix to Register Book). Victoria St. Wks.

Surveyed Afloat or in Dry Dock? Both. Name of Docks Fish Dry Dock. Destined Voyage Fishing.
WB=CellDBorDBa feet; uE&B feet; f feet; }
total capacity tons. FPT tons; APT tons; MT feet tons. }
N.B.—All alterations in the existing records should be underlined.
If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.
Last Report, No. Port
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
CHARACTER. 100 A1
* for Special Survey. Date of last Survey and of Periodical Surveys.
STM TRAWLER.
(CLASS CONTEMPLATED)
Society's Freeboard (if assigned) as painted on Ship and now verified

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined? Was a damage report made by anyone else? If so, by whom?
REPAIRS, OR EXAMINATION AS PER RULE, FOR Completion of 1st. Entry. No Docking.

The engines and boiler placed on board the vessel, and the casings, and deck plating in way of boiler, placed in position, riveted and Caulked. Foremast fitted of P. Pine, 41'0" above deck, and 13" dia at partners. Rigging to this mast of steel wire, as follows:- 3 Shrouds each Side 2 3/4", topmast Stay 2 1/4", forestay 3 1/4", 2 preventer forestays 2 1/2". Mizzen Rigging:- 2 Shrouds each Side 2 1/4", 2 forestays 2 1/4", and 2 preventer backstays 2 1/4". all of steel wire. Trawl winch placed on board and Secured in position. Docking. Vessel placed in dry dock. Bottom and rudder cleaned, examined, and coated.

| SUMMARY OF DAMAGE REPAIRS:- | Plates. | Frames. | R. Frames. | Floors. | Beams. | Str. Plates. | Dk. Plates. | Other Items:- |
|--------------------------------|---------|---------|------------|---------|--------|--------------|-------------|---------------|
| Renewed | | | | | | | | |
| Removed and Faired or Repaired | | | | | | | | |
| Faired or Repaired in place | | | | | | | | |

| PRESENT CONDITION OF THE | Stringers | Dblng. Plates under Sounding Pipes | Copper, or Y.M. of Wood Vessels |
|--------------------------|-----------|------------------------------------|---------------------------------|
| Decks | good | good | (state if on felt.) |
| Caulking of Decks | " | " | When put on, Month |
| Waterways | " | " | Boat |
| Samings | " | " | Masts, &c. |
| Beams & Fastenings | " | " | Condition, how ascertained |
| Outside Plating | good | " | (State if wedges removed) |
| Caulking of ditto | " | " | Sails |
| Rivets | " | " | Equipment letter |
| Breasthooks & Crutches | " | " | Anchors, No. of |
| Transoms | " | " | Cables (state if now ranged) |
| Side Frames | " | " | " length (on board) |
| Decks | " | " | " Rule length |
| Beams | " | " | Hawser & Warps |
| Stringers | " | " | Standing & Running Rigging |

General Observations, Opinion as to Class, Recommendation, &c.:-
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus for example:- "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,11," or "to remain as classed and to have record of survey, 1,11, and the notations of ss No. 1-11 and ptND11, &c."
This report is forwarded for the information of the Committee.

Survey Fee (per Section 28) £ : Fees applied for, 19
Special Damage or Repair Fee (if any) £ : Received by me, 19
C. 4. Working Expenses (if chargeable) £ :
and Surveyor's Fee (if any) £ :
Committee's Minute TUE. JAN. 21. 1913
Character Assigned 100 A1
STM Trawler