

STERN FRAME AND RUDDER
PARTLY CORRECTED.

Translation of Japanese.

(A)

Note

1. Tap bolt marked W & X to be lightly welded at heads after fitting.
1. Inside doublings (1" & 0.7" thick) can be renewed when threads worn.

(B)

Tables corrected.

(C)

Detailed plan of Top Cover.

(D)

Rudder shaft, top flange.



© 2021

Lloyd's Register
Foundation

007352-007362.0003