

5m, 5, 29,

ARAUCO

D 105 T

2 DEC 1930

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Steel Sc. Sr. "BOUSSOLE" Rpt. Bdx. No. 4135

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

Nature of Survey

The class is subject to indented plating being dealt with and a ventilator coaming of Rule scantling fitted to the powder magazine.

The Bordeaux Surveyor now reports the vessel placed in dry dock, bottom cleaned and coated.

The winch platforms in the forward and after wells have been linked up with the existing bridge by closing in the shell plating and deck in accordance with approved plans and Nos. 2 and 4 hatchways reduced in width and trunked to the extended bridge deck.

Owing to damage through fire and collision 1 shell plate has been renewed and repairs effected to shell plating, frames, deck, after bulkhead of No. 2 hold and minor repairs carried out.


The ventilator coaming to the powder magazine has been removed and the opening plated over.

It is submitted the vessel appears worthy to remain as classed with record of survey 11.30, without special condition.

100A1 )  
11.30 Bdx. ) without etc.

wh  
1.12.30.

Amend - P30' Ba 22' B103' Bf 22' F 35'  
to - P 30' B 215' F 35'.



© 2021

Lloyd's Register  
Foundation

007352-007362-0220