

to Chief Surveyors.....

Received from Chief Surveyors.....

SEL'S NAME ILLENAO

Report L.A.N. No. 2662

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

re of Survey. DOCKING

When due.....

*Subject to the rudder mainpiece E.W. 2-31. 3-34. 6-35. 6-36. 6-37 + 6-38 and
stern frame (S.S) E.W. 9-40 being specially examined at the next dry docking.*

was
6-11-40



© 2020

Lloyd's Register
Foundation

003396-007402-0045