

M

8,46.

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME "PANUCO" REPORT L.A. No. 11548

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The class is subject to (45 fathoms of chain cable being supplied).

The Lloyd's Agent Surveyor at TAMPICO reports (5.47) this tanker afloat and a GENERAL EXAMINATION due 4.47 held.

It is submitted the vessel is eligible to remain as classed, subject as above and to have notation of "Examined 5.47" valid for 12 months assigned.

As now, subject.

"Examined 5.47".

PLATING TO BE DRILLED
AT NEXT SPECIAL SURVEY.

see letter
It is submitted the Surveyor be informed that this vessel requires 300 fathoms of chain cable and when last ranged (4.46) had 255 fathoms on board. It is concluded the length now reported, ie 720' refers to one side only but he should state if this is so and also furnish the total length on board.

WOT.
15.7.47
JRM

007403-007411-0138