

Also what special means, in the absence of internal examination, were adopted by the
to secure himself of the thorough efficiency of those parts of each Boiler?

Panuco

LA
~~Tempe~~ 115.48

LMC Survey now held (except steam pipes which
were tested 1.46)

It is submitted that this
vessel is eligible for LMC
RECORD. +LMC 5.47.

Noted in SRL. Steam pipes tested 2.46

Roll

28/7/47

007403-007411-0140

examined and found in good condition. The main condenser was tested and found