

1

How PANCO

Sent to Chief Surveyors.

Received from Chief Surveyors.

VESSEL'S NAME **Steel S.S. "ATLANTIC SUN"** Report **PHL** No. **3767**

For the CHIEF SHIP SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24-5-02.)

Nature of Survey

When due

Vessel requires to be dry docked for examination after grounding.

100 A.1. (steel) "Carrying Petroleum in Bulk"

2 Dks (steel) & Webframes. "Longitudinal Framing"


Cell DB & E & B 60' 259 t.

FP 222 t. APT 57 t.

FK. 17 BH. (13 BH is upper dk. & 4 BH. is 2nd dk) pr. com A & C. P.

1133', B 36', F 40'. Machinery aft.

Subject to vessel being dry docked at the first convenient opportunity.



© 2021

Lloyd's Register Foundation

007403-007411-0142