

s/s "Indorita." & "Eldorita."

It is submitted that a copy of the Owners' letter be forwarded to the Liverpool Surveyors & they should be requested to explain why the petrol pumps referred to therein could not be sanctioned for these vessels.

Lloyd's Register
Foundation
1/2/22

007439-007447-0085