

of Surveyors _____

Received from Chief Surveyors _____

S NAME Steel S. Motor "INDORITA". Report Liv. No 81858

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement. -- Extract from Sub-Committee's Report, 24.5.92.)

Survey _____ When due _____

Telegrams from the Liverpool Surveyors state an additional side keelson forward and strengthening to the forecastle deck beams required to be fitted, will be completed on the 6th. instant, and it is submitted for consideration whether the class might be inserted in the re-print of the Register Book, but the certificates retained until a satisfactory report has been received. (*see letter received 10.5.41*)

✕ 100 A.1. (Steel).



1 Dk. (Steel).

FPT 30t., APT 25t.

BK 6", 3 BH. Lloyd's A. & C.P., Q35', F21', Mch. aft.

Date of Build 8.20.

The Certificate of Classification, to be endorsed
"Cargo battens not fitted," and the same
notation to be printed in the Register Book.

 
5. 5. 21.

The Surveyors should state whether the record of "pt. Cem."
"pt. Asp." should be made in this case.



© 2021

Lloyd's Register
Foundation

007439-007447-0017