

DISCLOSED SECTION

Rpt. S.

No. 444
(Received at London Office)

No. 117396

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report... 19... When handed in at Local Office... 19... Port of London

No. in Reg. Book. 19197. Survey held at on the Wood, Iron or Steel of S.S. "CHRYSANTHI" Date, First Survey... Last Survey... (No. of Visits...)

TONNAGE: GROSS 655, UNDER DK. 482, NET 289. Built at Harwich By whom Van Vleet & Co. Owners Messrs. Sideratos. Managers... Port belonging to Piraeus

Surveyed Afloat or in Dry Dock? Name of Dock... Destined Voyage... Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER * for Special Survey Date of last Survey and of Periodical Surveys	Machinery and Boiler Surveys (Including date of N.B., if any)
+ 100 A1	+ Aug 1. 46
3.48.	Bd. 3. 48
H. Pres. 2nd 3 - 12.36	C.L. 4.49
by Ant No 2-46.	
Change bottom not done.	

N.B.—All alterations in the existing records should be underlined.
Last Report, No. 16906 Port Amm

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined. Society's Freeboard (if assigned) as painted on Ship and now verified

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed ...								
Removed and Faired or Repaired								
Faired or Repaired in place ...								

PRESENT CONDITION OF THE	
Decks	Bulkheads
Caulking of Decks	Ceiling
Coamings	Cement or Asphalt
Beams & Fastenings	Rudder
Outside Plating	Steering gear and its connections
" " in way of sidelights	Windlass
Frames	Have pumps been examined and found efficient?
Reverse Frames	Have Sluice Valves been examined and found efficient?
Longitudinals	Have Watertight Doors been examined and found efficient?
Transverses	Have Ventilators and their Coamings been examined and found efficient?
Floors	Air and Sounding Pipes
Keelsons	Doubling Plates under Sounding Pipes
Stringers	Engine Room Skylights
Inner Bottom Plating	Coal Bunkers, Openings, Covers, &c.
Have the Tanks been examined Internally?	Oil Bunkers
Have the Tanks been tested?	Scuppers
	Cargo Hatchways
	Hatches
	Planking
	Caulking
	Treenails
	Breasthooks & Stems
	Transoms, Pointers & Crutches
	Timbers of Frame at openings
	" " at other places
	Stringers, Clamps & Shelves
	Salting
	State if examined.
	Copper, or Y.M. (State if on Felt.)
	When fitted, Month Year
	Boats
	Masts, Yards, &c.
	Condition, how ascertained (State if wedges removed.)
	Equipment letter
	Anchor, No. of
	Cables (State if now ranged)
	" length mean diamr. (on board.)
	" Rule length size
	Chain Locker
	Hawsers & Warps
	Standing and Running Rigging
	Sails

General Observations, Opinion as to Class, Recommendation, &c. :- State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Survey Fee (per Section 29)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 29)	£	:	:	19
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19

Committee's Minute. FRI. 22 JUL 1949. Character Assigned. Surveyor to Lloyd's Register of Shipping. Lloyd's Register of Shipping. General Committee. Thursday, 28th July, 1949. Classing Committee's decision confirmed 28.6.

15 JUL 1949

117396

No. 444

007448-007455-0160