

1m.7.42.

Cook, Welton & Gemmell Ltd., Beverley.

Yard No. 729.

F.E.

How Fort Malbouquet

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME "GILSAY" REPORT Hul. No. 52396

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Long. No. 2250

Depth "d" -

2nd Long. No. 6375

Proportions = $\frac{L}{D}$ 10.0

Framing Angle framing as approved

Sheerstrake As approved

This steam trawler for the Admiralty is a sister vessel to the
 "LUNDY", "ANNET", "BRYHER", "FARNE", "CALVAY", "FUDAY" etc.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ~~El~~100A- "Stm Trawler" "For Government Service".

FK, 7BH

F 27'

O.L. 164.5' ✓

E.S.D.

NOTE:- "Bituros" solution has been applied in the fresh water tanks. There is no reference to any cement having been laid on the bottom. The question of cementing the bottom, particularly under the boiler, will require to be considered in the event of "For Government Service" being deleted from the vessel's class.



© 2020

Lloyd's Register Foundation

007448-007455-0204

25.4.44