

4 E

22 MAR 1949

ed by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

SEL'S NAME LYGAS REPORT Bgn. No. 3270.

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement"—Extract from Sub-Committee's Report, 24/5/92.)

of Survey ~~REPAIRS TO ENGINES AND BOILERS DID TO BURN THROUGH~~

The electrical equipment of this vessel has been partly renewed; the electrical installation tested under working conditions and found satisfactory.

The generators and main switch board have now been altered from the original.



14.3.49

© 2020

Lloyd's Register  
Foundation

007448-007455-0237