

111 APR 1950

of Ship Surveyor.....

Received from Chief Ship Surveyor.....

NAME 'DON LUIS' REPORT Vpo. No. 2623

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. - Extract from Sub-Committee's Report, 24/5/52.

The Periodical Special Survey (C) due 1.48 was commenced Vpo. 5.48 and advanced Tal.11.48 and Vpo.12.48 & 12.49.

ACTION and NOTATION of 'ss. Vpo. 5.48' are DEFERRED for completion of Special Survey by 4.50.

Repairs are required to No.4. D.B. tank at the next dry docking.

TO COMPLETE S.S. :-

EXAMINE :- Peak spaces and plating in way of side-lights.

REPAIRS - as detailed in Vpo. Rpt.s Nos. 2474 & 2604.

The VALPARAISO Surveyor now reports (2.50), the vessel placed in dry dock, bottom coated, and the starboard anchor shackle pin renewed.

IT IS SUBMITTED the vessel is eligible to have record of docking survey 2.50, but further ACTION and NOTATION of 'ss. Vpo. 5.48' continue to be DEFERRED for completion of Special Survey by 4.50.

2.50 Vpo.



© 2021

*Handwritten signature and date:*  
Yiad  
5.4.50

S.S. Part Held

Lloyd's Register Foundation

007456-007464-0232