

11

-7 AUG 1941

a, 9, 37.

Inspected by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME

*Kizan Maru*Rpt. *Smk*No. *2639*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Docking

The *Shimonoseki* Surveyors report this vessel placed in dry dock, bottom cleaned and coated, ~~repairs to~~ and minor repairs effected.

It is submitted the vessel appears worthy to remain as classed with record of survey *4, 41* as recommended.

*100A1.**4, 41 Smk*

The Certificate of Classification to be endorsed "Cargo holdens not fitted" in *taxendocks* and the notation to be entered in the Register Book.

The Surveyor should be informed their recommendation regarding the supply of 1 1/2 fathoms of chain cable (as per SRL) is not understood as there is no record in this office of such deficiency.

survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."