

n.7.41.

as {  
d }

2 OCT 1941

Report to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME ARCHER REPORT Lon No. 109526A

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey ..... When due .....

due 6.41.

The Screw Shaft Survey became

The Owners now write that it is not intended to continue the classification of this tug in the Society's Register Book.

It is accordingly submitted the class of this vessel be withdrawn from the Register Book and three dots (...) be inserted in lieu, indicating withdrawal of class at Owners' request.

Withdraw class.  
Insert ...



29.9.41 © 2020

Lloyd's Register  
Foundation

007496-007505-0054

W. L. K. Scott

Locker .....