

(Received at London Office)

No. 109526A

SURVEY FOR REPAIRS, &c

held in at Local Office

Port of London

Date, First Survey

Last Survey

10 1941

~~DECLASSED~~
~~CANCELLED~~

Book No. 1054
on the Iron or Steel Tug

"M.S.C. ARCHER"

(No. of Visits)

YEAR

MONTH

When 1938

TONNAGE:-

Built at Leith

By whom Henry Robb, Ltd.

GROSS 144

Owners Manchester Ship Canal Co.

Owners' Address

UNDER DECK 142

Managers

Port belonging to Manchester

Surveyed Afloat or in Dry Dock?

Name of Dock

Destined Voyage

Cell DBor DBa feet; uE&B feet; f feet }
total capacity tons. FPT tons; APT tons; MT feet tons. }

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER. Date of last Survey and of Periodical Surveys.	Machinery and Boiler Surveys (Including date of N.B., if any).
+100A - For towing services 6.38	+Lmc 6.38 06

Only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.

Last Report, No. 19612 Port LH

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE

Decks	Bulkheads	Engine Room Skylights	Copper, or Y.M. (state if on Fell.)
Caulking of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year
Coamings	Cement or Asphalt	Oil Bunkers	Boats
Beams & Fastenings	Rudder	Scuppers	Masts, Yards, &c.
Outside Plating	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained (state if wedges removed.)
" " in way of sidelights	Windlass	Hatches	Equipment letter
Frames	Have pumps been examined and found efficient?	Planking	Anchors, No. of
Reverse Frames	Have Sluice Valves been examined and found efficient?	Caulking	Cables (state if now ranged)
Longitudinals	Have Watertight Doors been examined and found efficient?	Treenails	" length mean diamr (on board)
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stenson	" Rule length size
Floors	Air and Sounding Pipes	Timbers of Frame at openings	Chain Locker
Keelsons	Doubling Plates under Sounding Pipes	" " at other places	Hawsers & Warps
Stringers		Stringers, Clamps & Shelves	Standing and Running Rigging
Inner Bottom Plating		Salting (state if examined.)	Sails
Have the Tanks been examined internally?			
Have the Tanks been tested?			

General Observations, Opinion as to Class, Recommendation, &c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent on this survey, thus, for example: "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Survey Fee (per Section 20)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 20)	£	:	:	19
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19


Committee's Minute

FRI. 3 OCT 1941

Character Assigned

Withdraw class + insert (...)

Surveyor to Lloyd's Register of Shipping.



© 2020

Lloyd's Register Foundation

25 SEP

Item 2.41 - Transfer Ink. (Main and sub-panels to be used. The Surveyor is requested not to write on or below the space for Committee's Minutes.)

In Certificate required? If so, to be sent to

F500-50500-96700