

NOW DONE:- Vessel placed in dry dock. Bottom, stern frame and rudder cleaned,

Subject to the Solapiece of the Sternframe E.W. 3.30;
E.W. and reinforced 5.31 rewelded 6.32 + 4.40 being
Specially examined at next dry docking.

11

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME

VENICE MARU.

Rpt. No.

Kob. No. 11617

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Signature of Surveyor _____

The

Kobe

Surveyors report this vessel placed in

dry dock, bottom cleaned and coated, ~~repairs to~~

and ~~minor repairs effected.~~ The Stern frame, as above, is efficient

It is submitted the vessel appears worthy to remain as
classed with ^{out} record of survey ~~subject~~ as ^{above} recommended. *as recommended*

As now, subject re.

(Docking date 9.40)



© 2020
8.6.41

Lloyd's Register
Foundation

2nd of 170 2 due 5.41

007496-007505-0112

MADE IN
or Com

to be continued as classed without fresh record of survey, subject to the sole pi