

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

10th August 1922.

Dear Sirs,

I am in receipt of Mr. Bartlett's letter of the 3rd instant, enclosing a copy of the survey report (Rpt.10) issued by him on the S.S. No. 1 ("FULGOR") now being completed by the Cantieri Navali della Spezia, the contents of which have been very carefully noted.

I shall be glad if you will forward to this Office for examination samples of the defective rivets which have been removed, and also the results of the chemical analysis which you state is being carried out on the material.

When the vessel goes into dry dock for the renewal of the rivets, the shell plating and rivet points should be brushed down by a wire brush, examined, and, if considered satisfactory, carefully coated.

I may add that when the vessel is next dry docked she should be very carefully examined.

I am, Dear Sirs,

Yours faithfully,



© 2020
Secretary.

The Surveyors,

GENOA.

Lloyd's Register
Foundation
007496-007505-0257