

2m, 10, 39.

to Chief Surveyors

Received from Chief Surveyors

SHIP'S NAME

DESTINN

Report

LIV.

No. 114193

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

DOCKING

When due

*Subject to the misson mast being repaired at
the first opportunity.*

WAG
27.5.40

In S. R. L.

[Exon. in way of F.S.D. when device removed]



© 2020

Lloyd's Register
Foundation

007496-007505-0292