

5c.1.14.

F.E.

Received by Chief Ship Surveyor 21.10.14

Received from Chief Ship Surveyor

VESSEL'S NAME

Sheers

Destinn

Rpt.

Intl

No. 28009

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

35.41

Depth "d"

12.25

Framing: Table No.

3 page 10

Description

Single angle as approved

Longitudinal No.

4143

Proportions

Length

8.6

Depth

~~Deck~~ Sheerstrake

56 of an inch instead of 34 as required.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ✱ 100A-1 (Steel) "Steam Trawler" as recommended.

✱ 100A-1. (Steel) Ocean Trawler

1 Dr

BK. 7½". 4BK. Cam Lugs across @ 61'



© 2020

Lloyd's Register  
Foundation

007496-007505-0297

BEAMS, Second Deck, Single Angle, Bulb  
Angle, Plate, Tee Bulb, or Channel

Deck. Material & thickness  
Poon Deck Stringer Plate, breadth & thickness