

DISCLOSED SECTION. No. 448. SECTION No. 448

Rpt. 8.

(Received at London Office)

No. 117407 A

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report... 19... When handed in at Local Office... 19... Port of LONDON

No. in Reg. Book. Survey held at... Date, First Survey... Last Survey... 19...

58396 on the Wood, Iron or Steel S/S ESSO BALTIMORE

TONNAGE: GROSS 7949, UNDER DK 6985, NET 4711. Built at Sparrows Pt. Md. By whom Bethlehem S.P. Corp. Ltd. When 1938 - 9

Owners Standard Oil Co (New Jersey) Owners' Address... Managers... Port belonging to Wilmington Del.

Surveyed Afloat or in Dry Dock? Name of Dock... Destined Voyage

Cell DBor DBa... feet; uE & B... feet; f... feet. total capacity... tons. FPT... tons; APT... tons; MT... feet... tons.

N.B. All alterations in the existing records should be underlined.

Last Report, No. 8624 Port Bal

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER	Machinery and Boiler Surveys (including date of N.B., if any)
100 A1	LMC 2-47
H-48	BS 2-48
SS GAL - 2-47	NTS 4-48 (CA)
Carrying petroleum in bulk	
Fitted for oil fuel 9.98 FP above 150°F	
P2 Elec. welded.	

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

Society's Freeboard (if assigned) as painted on Ship and now verified WTB ft ins.

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS :-

	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed ...								
Removed and Faird or Repaired								
Faird or Repaired in place ...								

PRESENT CONDITION OF THE

Decks	Bulkheads	Engine Room Skylights	Copper, or Y.M.
Caulking of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	(State if on Felt)
Coamings	Cement or Asphalt	Oil Bunkers	When fitted, Month Year
Beams & Fastenings	Rudder	Scuppers	Boats
Outside Plating	Steering gear and its connections	Cargo Hatchways	Masts, Yards, &c.
" " in way of sidelights	Windlass	Hatches	Condition, how ascertained
Frames	Have pumps been examined and found efficient?	Planking	(State if wedges removed.)
Reverse Frames	Have Sluice Valves been examined and found efficient?	Caulking	Equipment letter
Longitudinals	Have Watertight Doors been examined and found efficient?	Treenails	Anchors, No. of
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stimson	Cables (State if now ranged)
Floors	Air and Sounding Pipes	Transoms, Pointers & Crutches	" length mean diamr.
Keelsons	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	(on board.)
Stringers		" " at other places	" Rule length size
Inner Bottom Plating		Stringers, Clamps & Shelves	Chain Locker
Have the Tanks been examined internally?		Salting	Hawsers & Warps
Have the Tanks been tested?		State if examined.	Standing and Running Rigging
			Sails

General Observations, Opinion as to Class, Recommendation, &c. :- State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example :- "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Survey Fee (per Section 29)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 29)	£	:	:	19
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19

Committee's Minute. FRI. 29 JUL 1949. Character Assigned. Withdraw class & insert (...) Ltd. Surveyor to Lloyd's Register of Shipping. Lloyd's Register General Committee Thursday 17 September 1949. Classing Committee decision confirmed. P.E.C.

2011.8.17. - Transfer Ink. (MADE AND PRINTED IN ENGLAND.)

Is certificate required? If so, to be sent to

410-935700-875700